


# **SYN- OXIDE**

## **Super Synthetic Anti Corrosive Oxide Paint Lead Free**



**Red**

**Green**

**Dark Green**

**Grey**

**Black**

**Farm buildings - Hay barns - Corrugated iron roofs  
ALL STRUCTURAL STEEL WORK**

**» HIGH PERFORMANCE**

**» LEAD FREE RUST INHIBITING**

**» COATING FOR PROTECTION**

**OF ALL STEEL SURFACES**

**WHERE LONG TERM**

**DURABILITY IS A PRIME**

**CONSIDERATION**

**AVAILABLE SIZES**

**1 L 2,5 L 5 L 20 L**



**Laydex Ltd**

*Allied Industrial Estate*

*Kylemore Road, Dublin 10*

*Tel: 00 353 (0)1 6426600*

*Fax: 00 353 (0)1 6426601*


*Email: sales@laydex.ie*

*Web: www.laydex.ie*

**Laydex**  
Building Solutions

# SYN- OXIDE

## Super Synthetic Anti Corrosive Oxide Paint Lead Free



**Red**

**Green**

**Dark Green**

**Grey**

**Black**

**Farm buildings - Hay barns - Corrugated iron roofs  
ALL STRUCTURAL STEEL WORK**

### APPLICATION

Fresh galvanised corrugated iron, should be allowed to weather for approx. 12 month. When exposed over this period of time, oxide salts and contaminants from the atmosphere will form on the surface. No painting should be undertaken until this is removed, using a stiff bristle brush and plenty of clean water. Be sure that the surface then it's completely dry. Work should never be undertaken except during fine, dry, warm weather. Do not apply late in the day if there is the slightest risk from fog or mist. Supplied ready for use. If necessary thin with white spirit or sub turps. Thinning should be kept to a minimum. Apply by brush or spray. 1 litre will cover up to 13 square meters.

### PREPARATION

Suitable for use on farm buildings, hay barns, corrugated iron roofs, and all structural steel work. Syn Oxide can be used as a general purpose protective coating on any type of normally prepared surface, so long as it is sound clean, dry and free of contaminants. Oil and grease must be carefully removed using white spirits and then wiped free of contaminated white spirit using clean cloths. Remove all scale and rust by scraping and wire brushing or other conventional means. If the surface has been previously painted any loose or defective paint must be completely removed back to the bare metal.

**PRIME BARE METAL BEFORE APPLICATION!**

### Laydex Ltd

Allied Industrial Estate  
Kylemore Road, Dublin 10  
Tel: 00 353 (0)1 6426600  
Fax: 00 353 (0)1 6426601  
Email: [sales@laydex.ie](mailto:sales@laydex.ie)  
Web: [www.laydex.ie](http://www.laydex.ie)

